

BEHR PREMIUM® Concrete & Masonry Bonding Primer

No. 880 Clear

- Interior/Exterior
- Helps Prevent Peeling of Topcoats
- Easy to Apply
- Promotes A Uniform Topcoat Finish









PRODUCT DRIES CLEAR- IT WILL LOOK MILKY IN CAN AND AT INTIAL APPLICATION.

CAUTION: Surfaces may become slippery when wet. Use caution when walking on surface when moisture is present.

WHERE TO USE

Uncoated Interior or Exterior surfaces such as Concrete, Masonry, Stucco, Cinder Block and any Porous Stone or Brick. Not designed for use on wood, metal or silicone treated surfaces. Do not use on coated surfaces. Use only on porous surfaces.

NOTE: SOME SURFACES MAY APPEAR SLIGHTLY DARKER AFTER PRODUCT DRIES.

PREPARATION† (Proper Surface Preparation is Required.)

- All surfaces must be clean, sound, dry and free of any dirt, oil and grease.
- New concrete must cure for a minimum of 30 days prior to priming.
- · Patch all holes and cracks and allow to dry.
- For touch-ups where surface coatings have failed, completely remove all loose or peeling paint.
- Do not apply over previously coated surfaces.
- Use a paint stripper to remove any previous coatings or sealers.
- · Clean and etch surface using a product such as a muriatic acid etcher (read and follow all manufacturer's label directions) to achieve a textured profile similar to 150 grit sandpaper.
- Wipe your fingers over the clean, dry floor to check for dust or powder. Ensure there is no residue on your fingers that may have been left from the etcher. If residue is found, rinse the surface to remove residue. Allow the surface to dry completely. Sprinkle a few drops of water onto the surface. If water is quickly absorbed and the surface feels like150 grit sandpaper, the surface is ready. If not, re-etch.

APPLICATION

- · DO NOT THIN.
- · Stir primer thoroughly before and occasionally during application.
- Use product when air and surface temperatures are between 50-90° F (10-32° C).
- Apply using a high quality pump sprayer, 1/4" 3/8" nap roller, nylon/polyester brush or a pad applicator.

DRY TIME

· Longer dry time required in cooler temperatures and in higher humidity. Must apply a topcoat after at least 4 hours, but before 30 days.

DISPOSAL

• Do not use soap and water to clean brushes or other applicators as they will become gummy. Properly dispose of all soiled rags. To recycle or properly dispose of product in your community, contact your household refuse collection service.

LIMITED WARRANTY

Visit behr.com/warranty or call 1-800-854-0133 Ext. 2 for more information.

† WARNING! If you scrape, sand or remove old paint, you may release lead dust, LEAD IS TOXIC. Contact the National Lead Information Center at 1-800-424-LEAD or log on to www.epa.gov/lead.

WARNING Cancer and Reproductive Harm www.P65Warnings.ca.gov

CAUTION! IRRITANT! HARMFUL IF SWALLOWED. MAY CAUSE EYE, NOSE AND THROAT IRRITATION.

AVOID CONTACT WITH SKIN AND EYES AND AVOID BREATHING OF VAPORS AND SPRAY MIST. WEAR EYE PROTECTION AND PROTECTIVE CLOTHING. USE ONLY WITH ADEQUATE VENTILATION. TO avoid breathing vapors and spray mist, open windows and doors or use other means to ensure fresh air entry during application and drying. If you experience eye watering, headaches or dizziness, increase fresh air. If properly used, a respirator (NIOSH approved for organic vapor with P series particulate pre-filter) may offer additional protection; obtain professional advice before using. A dust mask does not provide protection against vapors. Avoid contact with eyes and skin. Wash thoroughly after handling. Close container after each use. **FIRST AID:** If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical assistance immediately. In case of eye contact, flush immediately with plenty of water for at least 20 minutes and get medical attention; for skin, wash thoroughly with soap and water. If swallowed, get medical attention immediately. CAUTION: KEEP OUT OF REACH OF CHILDREN - DO NOT TAKE INTERNALLY.

