



## BEHR® FAST DRYING OIL-BASED POLYURETHANE

No. B7100 Series

Available in  
Satin, Semi-Gloss,  
Gloss, and Matte

- Durable Clear Protective Finish
- Recoat in 2 Hours
- Resists Stains and Scratches
- Self-Leveling, Smooth Finish
- Protects & Beautifies Interior Wood
- Dries to Touch in 2 Hours



Prep Before Use



2 Coats Required  
3 Coats if Desired



Spread Rate:  
125 Sq. Ft. / Qt.



Clean-Up:  
Mineral Spirits  
or Paint Thinner

### READY TO USE. PROTECT FROM FREEZING.

**WHERE TO USE:** Properly prepared interior bare or stained surfaces such as furniture, moldings, cabinets, trim, wood doors and residential hardwood floors.

**CAUTION:** Top coated surfaces may be slippery when wet.

**SURFACE PREPARATION\*** (The following steps are recommended for best results.) For refinishing, remove all wax or cleaner build-up with a wax stripper or degreaser prior to sanding. Sand all surfaces in the direction of the wood grain to desired smoothness. DO NOT USE steel wool. Remove all dust from sanded surfaces and clean with tack cloth.

**APPLICATION** Do not shake or thin. Do not apply in direct sunlight or in temperatures below 55°F (10°C) or above 90°F (32°C). Stir thoroughly prior to and during use. If wood stain color is desired, apply BEHR® Wood Stain. Follow all label instructions. Using a high quality natural bristle brush, dip approximately an inch into the can, gently tapping it against the inside to remove any excess. Apply a thin, even coat following the direction of the grain making sure to maintain a wet edge. To minimize the brush marks and bubbles after staining application, tip off the surface by holding the brush at a 45 degree angle and lightly run the bristles over the entire length of the wood. Floor Application: use a lambswool or synthetic pad applicator or synthetic bristle brush and maintain a wet edge to avoid lap marks. For maximum durability, 3 coats are required. Do not puddle, over-brush or overlap finishes. Sand lightly between coats with fine sand paper. Remove all dust prior to applying additional coats.

**DRY TIME** Dries to the touch in 2 hours. Sand or Recoat: 2 - 4 hours. After final coat, allow 12 - 24 hours before light use. Fully cured: 3 - 4 days after final coat.

**DISPOSAL** For disposal of empty containers and unused product, contact your household refuse collection service.

**LIMITED WARRANTY** Visit [behr.com/warranty](http://behr.com/warranty) or call 1-800-854-0133 Ext. 2 for more information.

**\*WARNING** If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. Contact the National Lead Information Center at 1-800-424-LEAD or log on to [www.epa.gov/lead](http://www.epa.gov/lead).

**WARNING** Cancer and Reproductive Harm  
[www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**IMPORTANT! STORAGE AND DISPOSAL: DANGER!** Rags, steel wool and waste soaked with BEHR OIL-BASED FAST DRYING POLY may spontaneously catch fire if improperly discarded or stored. To avoid a spontaneous combustion fire, immediately after use, place rags, steel wool or waste in a sealed water-filled, metal container. Do not store unused product inside the home. For disposal guidance, contact your household refuse collection service, fire department, county or state government control agency.

**DANGER! HARMFUL OR FATAL IF SWALLOWED. COMBUSTIBLE LIQUID AND VAPOR. MAY CONTAIN: HYDROTREATED LIGHT DISTILLATES, ALUMINUM ALKOXIDE, NAPHTHA (PETROLEUM) and CRYSTALLINE SILICA. CAUSES DAMAGE TO ORGANS (CENTRAL NERVOUS SYSTEM) THROUGH PROLONGED OR REPEATED EXPOSURE. CAUSES SERIOUS EYE IRRITATION AND IRRITATES SKIN, NOSE, AND THROAT. MAY CAUSE AN ALLERGIC SKIN REACTION. NOTICE:** Reports have associated repeated prolonged occupational exposure to solvents with permanent brain damage. Intentional misuse by deliberately concentrating and inhaling contents may be harmful or fatal. Keep away from heat and flame. Do not smoke. Prevent build-up vapors by opening all windows and doors to achieve cross-ventilation. **USE ONLY WITH ADEQUATE VENTILATION.** To avoid breathing vapors and spray mist, open windows and doors or use other means to ensure fresh air entry during application and drying. If you experience eye watering, headaches or dizziness, increase fresh air. If properly used, a respirator (NIOSH-approved for organic vapor with P series particulate pre-filter) may offer additional protection; obtain professional advice before using. A dust mask does not provide protection against vapors. Avoid contact with eyes and skin. Wash thoroughly after handling. Close container after each use. **FIRST AID:** If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical assistance immediately. In case of eye contact, flush immediately with plenty of water for at least 20 minutes and get medical attention; for skin, wash thoroughly with soap and water. If swallowed, do not induce vomiting. Call physician immediately.

**KEEP OUT OF REACH OF CHILDREN-DO NOT TAKE INTERNALLY.**

**PLEASE SEE PRODUCT LABEL FOR SPECIFIC WARNINGS. WARNINGS MAY VARY BETWEEN PRODUCTS AND OR COLORS.**



©2021 Behr Process Corporation  
Santa Ana, CA 92705 U.S.A. • [behr.com](http://behr.com)  
V.O.C. (C.O.V.) <450 g/L • REV. 9/21