



BEHR® COPPER FORCE™ Interior Eggshell Enamel

No. 2190 Tintable White
No. 2193 Deep Base

EPA Registration No. 32273-10

- Virucidal & Antibacterial Paint
- Durable, Long Lasting Finish
- Mildew Resistant Paint Finish
- Paint & Primer[◇]
- Excellent Hide
- Low Odor
- 100% Acrylic
- Limited Warranty*

[◇] A primer coat may be needed on some surfaces. See back label for details.

TINTABLE WHITE: READY TO USE OR ADD TINTING COLORANTS.
DEEP BASE: DO NOT USE WITHOUT THE ADDITION OF TINTING COLORANTS.

PRODUCT USES

For application to hard, non-porous interior walls, ceilings, doors and trim in residential, commercial and institutional settings. Ideal for use in homes, offices, clinics, nursing homes, athletic facilities, schools, community centers, daycare centers, assisted living communities, hotels and resorts. Also suitable for non-critical areas of hospitals, such as examination rooms, waiting rooms, hallways and walkways. See SURFACE CARE AND MAINTENANCE for proper care and cleaning information. **DO NOT USE ON FLOORS OR ON EXTERIOR SURFACES.**

DIRECTIONS FOR USE

It is a violation of federal law to use this product in a manner inconsistent with its labeling.

SURFACE PREPARATION*

- All surfaces should be clean, free of dust, chalk, oil, grease, wax, polish, mold and mildew stains, loose and peeling paint, rust, and all other foreign substances. Scuff sand glossy surfaces and repair imperfections. Allow new concrete, plaster and masonry to cure for 30 days before painting.
- Although this product is a paint & primer (self-priming — first coat is the primer and the second coat is the finish) over most properly prepared surfaces, certain substrate and exposure conditions, as well as project requirements, may necessitate the use of substrate-specific or solution-driven primers.

***ATTENTION** If you scrape, sand or remove old paint, you may release lead dust. **LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE.** Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Center at 1-800-424-LEAD or log on to www.epa.gov/lead.

APPLICATION

- For best results, apply when air, material and surface temperatures are between 50°F and 90°F.
- Stir paint occasionally. Intermix containers of same product to ensure color and sheen uniformity.

- Do not thin. Product is formulated at package consistency.
- Apply two coats by brush (nylon/polyester), roller (3/8" – 1/2" nap) or airless sprayer (.015" – .019" spray tip) at a coverage of 250 – 400 sq ft per gallon. Coverage depends on application method and substrate porosity. Certain colors may require additional coats for complete hide.
- Dries to touch in 1 hour; recoat after 2 hours @ 77°F and 50% RH. Drying and recoat times are dependent on temperature, humidity and film thickness.
- Clean all tools and equipment with soap and water.

To avoid breathing vapors and spray mist, open windows and doors or use other means to ensure fresh air entry during application and drying. If you experience eye watering, headache or dizziness, increase fresh air. If properly used, a respirator (NIOSH approved for organic vapor with P series particulate pre-filter) may offer additional protection; obtain professional advice before using. A dust mask does not provide protection against vapors.

STORAGE AND DISPOSAL

Do not contaminate water, food, or feed by storage and disposal. **PESTICIDE STORAGE:** Store away from food and pet food. Open dumping is prohibited. Keep container closed when not in use. Do not transfer contents to other containers. Protect pesticide containers from extreme heat and cold. **PESTICIDE DISPOSAL and CONTAINER HANDLING:** Nonrefillable container. Do not reuse or refill this container. If empty: Place in trash or offer for recycling if available. If partly filled: Call your local solid waste agency for disposal instructions. Never place unused product down any indoor or outdoor drain. Waste resulting from the use of this product may be disposed of on site or at an approved waste disposal facility.

SURFACE CARE AND MAINTENANCE

Periodic cleaning to remove dirt and stains is necessary for good sanitization and to assure the effective virucidal and antibacterial performance of the surface. Cleaning does not reduce the virucidal and antibacterial performance of the painted surface. To ensure continuous protection, repaint surface if film becomes damaged (peeled, cracked, etc.) or if paint becomes covered with oils, grease, wax, other paints and other foreign substances; or within 6 years.

Proper Surface Care and Use: The use of an antimicrobial treated surface is a supplement to and not a substitute for standard infection control practices; user must continue to follow all current infection control practices, including those practices related to cleaning and disinfection of environmental



surfaces. The painted surface material has been shown to reduce microbial contamination, but does not necessarily prevent cross contamination.

Cleaning Directions: Cleaning agents typically used on painted surfaces are acceptable. The appropriate cleaning agent depends on the type of soiling and the measure of sanitization required. The best way to wash painted surfaces is to use a soft damp cloth or sponge and a mild detergent solution (a small amount of dishwashing liquid in water). Gently wipe the soiled area (using the least amount of pressure) until the stain is removed. Allow the cleaning solution to do the work. Do not scrub the surface as this can actually cause the stain to spread. Rinse surface with clean water. Do not use harsh or abrasive cleansers or pads, which can scratch, burnish or damage the paint film. Consider using BEHR SWIPES Interior Wall Wipes for removing stubborn stains, such as lipstick and crayon. **DO NOT USE OXIDIZING CLEANERS/DISINFECTANTS, SUCH AS BLEACH AND HYDROGEN PEROXIDE, OR ENZYME-BASED CLEANING SOLUTIONS AS THEY WILL CAUSE DISCOLORATION AND REDUCE THE EFFICACY OF THE SURFACE.**

PRECAUTIONARY STATEMENTS

HAZARD TO HUMANS AND DOMESTIC ANIMALS. CAUTION HARMFUL IF ABSORBED THROUGH THE SKIN OR SWALLOWED. AVOID CONTACT WITH EYES, SKIN, OR CLOTHING AND AVOID BREATHING VAPORS AND SPRAY MIST. WEAR EYE PROTECTION, GLOVES AND PROTECTIVE CLOTHING. Wash thoroughly with soap and water after handling and before eating, drinking, chewing gum, using tobacco, or using the toilet. Remove and wash contaminated clothing before reuse. **DO NOT TAKE INTERNALLY. KEEP OUT OF THE REACH OF CHILDREN. FOR INTERIOR USE ONLY. PROTECT FROM FREEZING.**

ENVIRONMENTAL HAZARDS

Do not apply directly to lakes, streams, ponds, estuaries, oceans or other waters by cleaning of equipment or disposal of wastes. Dispose of paint debris in an approved landfill. Do not discharge effluent containing this product into lakes, streams, ponds, estuaries, oceans or other waters unless in accordance with the requirements of a National Pollutant Discharge Elimination System (NPDES) permit and the permitting authority has been notified in writing prior to discharge. Do not discharge effluent containing this product to sewer systems without previously notifying the local sewage treatment plant authority. For guidance, contact your State Water Board or Regional Office of the EPA.

For guidance, contact your State Water Board or Regional Office of the EPA.

***LIMITED WARRANTY** For six years from the date of purchase, Behr Process Corporation warrants to the original consumer purchaser, (1) that the product meets Behr Process Corporation's manufacturing specifications, and (2) the performance of this product when applied according to the label instructions and specifications. If this product is found not to perform as specified on the label, Behr Process Corporation will, at its option and upon presentation of proof-of-purchase (the original receipt), either furnish an equivalent amount of new product or refund the original purchase price of this product to you. **This warranty excludes (1) labor and costs of labor for the application or removal of any product, and (2) any incidental or consequential damages, whether based on breach of express or implied warranty, negligence, strict liability or any other legal theory.** Some states do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation or exclusion may not apply to you. To the extent permitted by applicable law, any implied warranties including the implied warranties of merchantability and of fitness for a particular purpose, are limited to the duration of this express warranty. Some states do not allow limitations on how long an implied warranty lasts, so the above limitation may not apply to you. This warranty gives you specific legal rights and you may also have other rights, which vary from state to state. **To obtain warranty service, call 1-800-854-0133.** Behr Process Corporation reserves the right to inspect any and all application of the product prior to processing your claim made under this warranty.

To consult with a Behr Paint Company Representative, call 1-800-854-0133 Ext. 2 (U.S.A. only).

ATTENTION This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm.

CONTAINS: CRYSTALLINE SILICA and TITANIUM DIOXIDE. USE ONLY WITH ADEQUATE VENTILATION. To avoid breathing vapors and spray mist, open windows and doors or use other means to ensure fresh air entry during application and drying. If you experience eye watering, headache or dizziness, increase fresh air. If properly used, a respirator (NIOSH approved for organic vapor with P series particulate pre-filter) may offer additional protection; obtain professional advice before using. A dust mask does not provide protection against vapors. **FIRST AID**

IF IN EYES: Hold eye open and rinse slowly and gently with water for 20 minutes. Remove contact lenses, if present, after the first 5 minutes, then continue rinsing eye. Call a poison control center or doctor for further treatment advice.

IF ON SKIN: Take off contaminated clothing. Rinse skin immediately with plenty of water for 20 minutes. Call a poison control center or doctor for treatment advice.

IF SWALLOWED: Call a poison control center or doctor immediately for treatment advice. Have a person sip a glass of water if able to swallow. Do not induce vomiting unless told to do so by a poison control center or doctor. Do not give anything to an unconscious person. Have the product container label with you when calling a Poison Control Center or doctor or going for treatment. For emergency information concerning this product, call the National Pesticides Information Center at 1-800-858- 7378, 6:30 AM to 4:30 PM Pacific time (PT), seven days a week. During other times, call the poison control center at 1-800-222-1222.

